

MCDONNELL DOUGLAS

Douglas Aircraft Company

28 February 1995
C1-Q6C-SL-95-046

California Regional Water Quality Control Board
Los Angeles Region
101 Centre Plaza Drive
Monterey Park, CA. 91754

Attention: Technical Support Unit

Subject: SUBMITTAL OF ANNUAL REPORT FOR NPDES PERMIT NO. CA
0001414 - COMPLIANCE FILE NO. 5999 FOR 1994

Attachments: 1) Tabular and Graphical Summaries of the Monitoring Data
Obtained During 1994 for Discharge Location 001

2) Annual Summary of the Quantities of Water Treatment
Chemicals Discharged During 1994

3) Copies of Laboratory Analyses

Gentlemen:

Douglas Aircraft Company herewith submits the annual report in accordance with the General Monitoring and Reporting Provision number 5999. The report contains tabular and graphical summaries of the monitoring data obtained during 1994 and a summary of the quantities of water treatment chemicals discharged during 1994. Copies of laboratory analyses are also attached.

All analyses were conducted by Truesdail Laboratories of Tustin, California, in accordance with the current EPA guideline procedures or as specified in the Monitoring Program.

Exceedances of oil and grease during various sampling events at the Permit Location have been attributed to the fact that this location receives little or no flow throughout the year, causing a buildup of these materials within the sampling location. Truesdail Laboratories has been instructed by Douglas Aircraft Company not to sample the location when no flow occurs.

"I declare under penalty of perjury that the foregoing is true and correct", executed on the 28th day of February, 1995.

Sincerely,



Scott Lattimore
Environmental Engineer
Safety, Health, and Environmental Affairs


3855 Lakewood Blvd., Long Beach, CA 90846-0001 (213) 593-5511 TELEX 67-4357

ANNUAL DISCHARGE SUMMARY NPDES #001* (1994)
DOUGLAS AIRCRAFT COMPANY TORRANCE, CA. FACILITY
NPDES CA0001414


CONSTITUENTS	JANUARY 1/31/94	FEBRUARY 2/25/94	MARCH 3/22/94	APRIL 4/15/94	MAY 5/26/94	JUNE 7/7/94	JULY 7/8/94	AUGUST 8/22/94	SEPTEMBER 9/13/94	OCTOBER 10/10/94	NOVEMBER 10/31/94	DECEMBER 12/1/94
TEMPERATURE (F)	62	65	66	72	74	68	68	70	70		65	57
pH			7.1			8			8.2	7.6		
BOD5 @ 20 C (mg/l)			ND			ND			23	4.7		
SETTLEABLE SOLIDS (ml/hr)			ND			ND			ND	ND		
OIL & GREASE (mg/l)			ND			11.4			21.7	17		
TOTAL SUSPENDED SOLIDS (mg/l)			ND			10			11	49		
CHROMIUM			ND			ND			ND	ND		
96 HOUR BIOASSAY (% survival)												100

* NO FLOW WAS MEASURED AT THIS LOCATION DURING ANY SAMPLING DATE


TEMPERATURE (F)
Annual Discharge Summary (1994)




pH
Annual Discharge Summary (1994)




BOD5 @ 20 C
Annual Discharge Summary (1994)




SETTLEABLE SOLIDS (mg/l)
Annual Discharge Summary (1994)




OIL & GREASE (mg/l)
Annual Discharge Summary (1994)



**TOTAL SUSPENDED SOLIDS (mg/l)
Annual Discharge Summary (1994)**




**CHROMIUM (mg/l)
Annual Discharge Summary (1994)**



McDONNELL DOUGLAS CORPORATION
Douglas Aircraft Company
Cooling Tower Product Usage
January 1, 1994 - December 31, 1994
Plant C-6, Torrance

<u>Product</u>	<u>Description</u>	<u>Gallons</u>	<u>Pounds</u>
2818	Microbiocide Stabilized Liquid Chlorine	50	540
2827	Scale/Corrosion Organophosphonate	75	705

TRUESDAIL LABORATORIES, INC.



CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931

14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company
Internal Mail Code 74-41
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Boramy Ith

REPORT DATE: April 12, 1994

RECEIVED: January 31, 1994

Water from Torrance Stormdrain
C-6 Facility - 1/31/94
P.O. No: T & M 25998C

Monthly Industrial Wastewater Analysis as Required by
NPDES Permit #CA0001414, January, 1994

RESULTSField Data

Flow, GPD

No Flow

Temperature, °F

62

pH, Units

8.76

Respectfully Submitted,
Truesdail Laboratories, Inc.


Thomas Herrin, Manager
Environmental Field Services



This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

REPORT

TRUESDAIL LABORATORIES, INC.



CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931

14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company
Internal Mail Code 74-41
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Boramy Ith

REPORT DATE: April 12, 1994

RECEIVED: February 25, 1994

Water from Torrance Stormdrain
C-6 Facility - 2/25/94
P.O. No: T & M 25998C

Monthly Industrial Wastewater Analysis as Required by
NPDES Permit #CA0001414, February, 1994

RESULTS

Field Data

Flow, GPD

No Flow


Temperature, °F

65

pH, Units

8.7

Respectfully Submitted,
Truesdail Laboratories, Inc.


Thomas Herrin, Manager
Environmental Field Services




This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

REPORT

TRUESDAIL LABORATORIES, INC.

CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931



14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company
Internal Mail Code 74-41
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Boramy Ith

REPORT DATE: March 31, 1994

RECEIVED: March 22, 1994

LABORATORY NUMBER: 68153

Water from Stormdrain #799
SAMPLE DATE: 03/21/94

First Quarter, 1994, Analysis as Required by NPDES Permit #CA0001414

RESULTS

Total Flow, GPD
Temperature, °F
, Units (EPA 150.1)

None
66
7.1

MILLIGRAMS PER LITER

PARAMETER	METHOD	DETECTION LIMIT	CONCENTRATION
Biochemical Oxygen Demand	405.1	2.0	ND
Oil & Grease	413.1	5.0	ND
Settleable Solids (ml/L/hr)	160.5	0.2	ND
Total Suspended Solids	160.2	4.0	ND
Chromium	200.7	0.01	ND

*ND= Not detected, below detection limit.

Respectfully Submitted,
Truesdail Laboratories, Inc.


Thomas Herrin, Manager
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

REPORT

TRUESDAIL LABORATORIES, INC.

CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931



14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company
Internal Mail Code 74-41
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Boramy Ith

REPORT DATE: July 14, 1994

RECEIVED: April 15, 1994

Water from Torrance Stormdrain
C-6 Facility - 4/15/94
P.O. No: T & M 25998C

Monthly Industrial Wastewater Analysis as Required by
NPDES Permit #CA0001414, April, 1994

RESULTS

Field Data

Flow, GPD

No Flow

Temperature, °F

72

pH, Units

8.3


Respectfully Submitted,
Truesdail Laboratories, Inc.

Thomas Herrin, Manager
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

BOE-C6-0212055

TRUESDAIL LABORATORIES, INC.



CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931

14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company
Internal Mail Code 74-41
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Boramy Ith

REPORT DATE: July 14, 1994

RECEIVED: May 26, 1994

Water from Torrance Stormdrain
C-6 Facility - 5/26/94
P.O. No: T & M 25998C

Monthly Industrial Wastewater Analysis as Required by
NPDES Permit #CA0001414, May, 1994

RESULTSField Data

Flow, GPD

No Flow

Temperature, °F

74

pH, Units

8.5

Respectfully Submitted,
Truesdail Laboratories, Inc.


Thomas Herrin, Manager
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

TRUESDAIL LABORATORIES, INC.

REPORT

CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931



14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company
Internal Mail Code C6-59
19503 South Normandie Ave.
Torrance, CA 90502
ATTN: Boramy Ith

REPORT DATE: July 14, 1994

RECEIVED: July 7, 1994

LABORATORY NUMBER: 69730

Water from Stormdrain, Torrance Facility
P.O. No: T & M 25998C

Second Quarter, 1994, Analysis as Required by NPDES Permit #CA0001414

RESULTS


Total Flow, GPD No Flow
Temperature, °F 68
pH, Units (EPA 150.1) 8.0

Parameter	Method	MILLIGRAMS PER LITER Detection Limit	Concentration
Biochemical Oxygen Demand	405.1	2.0	ND
Chromium	200.7	0.01	ND
Oil and Grease	413.1	6.0	11.4
Settleable Solids (ml/L/hr)	160.5	0.20	ND
Total Suspended Solids	160.2	4.0	10.0

*ND = Not detected, below detection limit



Respectfully Submitted,
Truesdail Laboratories, Inc.



Thomas Herrin, Manager
Environmental Field Services

This report applies only to the samples investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

REPORT

TRUESDAIL LABORATORIES, INC.

CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931



14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company
Internal Mail Code 9-20
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Michael Binder
SAMPLE DATE: 07/08/94
PERMIT NUMBER: NPDES # CA0001414
SITE I.D. #799 Stormdrain

REPORT DATE: Sept. 27, 1994

RECEIVED: July 11, 1994

LABORATORY NUMBER: 69766

Monthly Analysis as Requested

RESULTS

pH, Units (150.1)	8.0
Temperature, °F	68

*ND = Not detected, below detection limit




Respectfully Submitted,
Truesdail Laboratories, Inc.

Thomas Herrin
Thomas Herrin, Manager
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

REPORT

TRUESDAIL LABORATORIES, INC.



CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931

14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company
Internal Mail Code 9-20
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Michael Binder
SAMPLE DATE: 08/22/94
PERMIT NUMBER: NPDES # CA0001414
Next to Site #799

REPORT DATE: Sept. 27, 1994

RECEIVED: August 22, 1994

LABORATORY NUMBER: 70487

Monthly Analysis as Requested

RESULTS


pH, Units (150.1)

8.1

Temperature, °F

70

*ND = Not detected, below detection limit




Respectfully Submitted,
Truesdail Laboratories, Inc.

Thomas Herrin
Thomas Herrin, Manager
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

REPORT

TRUESDAIL LABORATORIES, INC.



CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931

14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Douglas Aircraft
3855 Lakewood Blvd
Long Beach, CA 90846
ATTN: Michael Binder

REPORT DATE: Sept. 29, 1994

RECEIVED: Sept. 13, 1994

LABORATORY NUMBER: 70787

SAMPLE DATE: 09/13/94
SITE ID: Torrance Stormdrain

MONTHLY/QUARTERLY ANALYSIS AS REQUESTED

RESULTS

pH, Units (150.1) 8.20
Temperature, °F 70

PARAMETER	METHOD	MILLIGRAMS PER LITER	
		DETECTION LIMIT	CONCENTRATION
Biochemical Oxygen Demand	405.1	2.0	23
Chromium, Total	200.7	0.01	ND
Oil & Grease	413.1	5.0	21.7
Settleable Solids	160.5	0.1 ml/L/hr	ND
Total Suspended Solids	160.2	4.0	11

*ND = Not Detected, below detection limit




Respectfully Submitted,
Truesdail Laboratories, Inc.

Thomas Herrin
Thomas Herrin, Manager
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

REPORT

TRUESDAIL LABORATORIES, INC.



CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931

14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Mcdonnell Douglas Aircraft
3855 Lakewood Blvd
Long Beach, CA 90846
ATTN: Michael Binder

REPORT DATE: October 27, 1994

RECEIVED: October 10, 1994

LABORATORY NUMBER: 71207

SAMPLE DATE: 10/10/94
SITE I.D. Torrance Stormdrain,
Next to Site #799

PERMIT NUMBER: 799

QUARTERLY INDUSTRIAL WASTEWATER ANALYSIS, AS REQUESTED

RESULTS

Total Flow (GPD) No Flow
pH, Units (150.1) 7.60

PARAMETER	METHOD	MILLIGRAMS PER LITER	
		DETECTION LIMIT	CONCENTRATION
Biochemical Oxygen Demand	405.1	2.0	4.7
Oil and Grease	413.1	5.0	17
Settleable Solids	160.5	0.1 ml/L/hr	ND
Total Suspended Solids	160.2	4.0	49
Chromium, Total	200.7	0.044	ND

*ND = Not Detected, below detection limit.

Respectfully Submitted,
Truesdail Laboratories, Inc.

Thomas Herrin

Thomas Herrin, Manager
Environmental Field Services




This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

REPORT

TRUESDAIL LABORATORIES, INC.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS
RESEARCH - DEVELOPMENT - TESTING
ESTABLISHED 1931



14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Mcdonnell Douglas Aircraft
3855 Lakewood Blvd
Long Beach, CA 90846
ATTN: Michael Binder

REPORT DATE: Nov. 08, 1994

RECEIVED: October 31, 1994

LABORATORY NUMBER: 71504

SAMPLE DATE: 10/31/94
SITE I.D. Torrance Stormdrain,
Next to Site #799
PERMIT NUMBER: NPDES #CA0001414

MONTHLY INDUSTRIAL WASTEWATER ANALYSIS, AS REQUESTED

RESULTS

Total Flow (GPD)


No Flow

pH, Units (150.1)

8.1

Temperature, °F

65




Respectfully Submitted,
Truesdail Laboratories, Inc.

Thomas Herrin
Thomas Herrin, Manager
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

REPORT

TRUESDAIL LABORATORIES, INC.



CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931

14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company
3855 Lakewood Blvd.
Long Beach, CA 90846
Attn: Scott Lattimore

REPORT DATE: Dec. 15, 1994

RECEIVED: Dec. 01, 1994

LABORATORY NUMBER: 71978

SAMPLE DATE: 12/01/94
PERMIT NUMBER: NPDES # CA0001414
SITE I.D. #799, Torrance Stormdrain

Monthly Analysis as Requested

RESULTS


pH, Units (150.1)


7.46

Temperature, °F

57


Respectfully Submitted,
Truesdail Laboratories, Inc.


Thomas Herrin, Manager
Environmental Field Services



This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

TRUESDAIL LABORATORIES, INC.



CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931

14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-156
FAX (714) 730-6462

CLIENT: McDonnell Douglas Aircraft
3855 Lakewood Blvd
Long Beach, CA 90846
Attn: Scott Latimore

REPORT DATE: Jan. 10, 1995

RECEIVED: Dec. 15, 1994


LABORATORY NUMBER: 77191-3

SAMPLE DATE: 12/15/94
SITE I.D.: Torrance Stormdrain

INVESTIGATION: 96-Hour Percent Survival Acute Aquatic Toxicity Bioassays

RESULTS

The sample demonstrated 100% survival in the undiluted effluent for a 96-Hour LC₅₀ greater than 100% undiluted effluent.



Respectfully Submitted,
Truesdail Laboratories, Inc.

Thomas Herrin
Thomas Herrin, Manager
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.